<u>September 2025 – Reservoir Roof Vent –</u> clear biological growth & clean pvc vent











October 2025 - Reservoir Inlet - clear overgrowth to prepare for paint, check for dry rot







October 2025 - Pumphouse Roof - new plywood sheets, trim, replace tiles w/ metal









October 2025 - Pumphouse & Reservoir Inlet - new paint







October 2025 – Reservoir Overflow – terminate between 12" – 24" above the ground surface.



